

Our chart below lists the connectors that we have tested.

○ : Crimping OK, X : Crimping impossible, Blank: Not yet tested

If your target connector is not found, please email us with your connector part number & the manufacturer name.

Use [Ctrl+F] for searching in PC or use "Find in Page" option for searching in a mobile phone.

| | Molex | | "ENGINEER" Crimp Tool Model Nos. | | | | | |
|----|-------------------|--------------|----------------------------------|--------|--------|-------|-------|-------|
| | Terminal Part No. | Old Part No. | PAD-11 | PAD-12 | PAD-13 | PA-09 | PA-20 | PA-21 |
| 1 | 501334-0000 | - | | | | | | |
| 2 | 501334-0100 | - | | | | | | |
| 3 | 501193-3000 | - | | | | | | |
| 4 | 78172-0410 | - | | | | | | |
| 5 | 78172-0411 | - | | | | | | |
| 6 | 502381-0000 | - | ○ | | | | | |
| 7 | 50753-8041 | - | | | | | | |
| 8 | 50641-8041 | - | | | | | | |
| 9 | 50753-8141 | - | | | | | | |
| 10 | 50641-8141 | - | | | | | | |
| 11 | 501930-1100 | - | | | | | | |
| 12 | 699 | - | | | | | | |
| 13 | 50079-8000 | - | | | | | | |
| 14 | 50058-8100 | - | ○ | | | ○ | | |
| 15 | 50079-8100 | - | ○ | x | x | ○ | | |
| 16 | 502579-0000 | - | ○ | | | | | |
| 17 | 503429-0000 | - | | | | | | |
| 18 | 502438-0000 | - | | | | | | |
| 19 | 502438-0100 | - | ○ | x | x | | | |
| 20 | 501647-1000 | - | | | | | | |
| 21 | 501648-1000 | - | ○ | x | x | | | |
| 22 | 501647-1100 | - | | | | | | |
| 23 | 56134-9000 | - | ○ | | | | | |
| 24 | 56134-9100 | - | | | | | | |
| 25 | 50212-8000 | - | | | | | | |
| 26 | 50212-8100 | - | | | | ○ | | |
| 27 | 59370-8000 | - | | ○ | | | | |
| 28 | 59370-8100 | - | | | | | | |
| 29 | 50011-8000 | - | | | | | | |
| 30 | 50011-8100 | - | ○ | x | x | ○ | | |
| 31 | 50351-8000 | - | | | | | | |
| 32 | 50351-8100 | - | ○ | ○ | x | ○ | ○ | ○ |
| 33 | 08-70-1039 | 5263PBT | | | | | | |
| 34 | 08-70-1040 | 5263PBTTL | ○ | x | x | ○ | ○ | ○ |
| 35 | 08-70-0064 | 5159T | ○ | ○ | x | | | |
| 36 | 08-70-0048 | 5159PBT | ○ | ○ | x | | | |
| 37 | 08-70-0069 | 5159TL | ○ | ○ | x | ○ | ○ | ○ |

| | | | | | | | | |
|----|-------------|----------|---|---|---|---|---|---|
| 38 | 08-70-0049 | 5159PBTL | ○ | ○ | x | | | ○ |
| 39 | 50802-8000 | - | | | | | | |
| 40 | 50802-9001 | - | ○ | | | | | |
| 41 | 50802-8100 | - | ○ | | | | | ○ |
| 42 | 50802-9101 | - | ○ | ○ | x | ○ | ○ | ○ |
| 43 | 503485-0000 | - | | | | | | |
| 44 | 50125-8000 | - | ○ | | | ○ | | |
| 45 | 50133-8000 | - | | | | | | |
| 46 | 50125-8100 | - | ○ | | | ○ | | |
| 47 | 50133-8100 | - | | | | | | |
| 48 | 50079-8000 | - | | | | | | |
| 49 | 50058-8000 | - | | | | | | |
| 50 | 50079-8100 | - | | | | | | |
| 51 | 50058-8100 | - | ○ | x | x | | | |
| 52 | 50012-8000 | - | | | | | | |
| 53 | 50012-8100 | - | ○ | | | | | |
| 54 | 50013-8000 | - | | | | | | |
| 55 | 50013-8100 | - | ○ | | | | | |
| 56 | 56086-8000 | - | | | | | | |
| 57 | 56086-8100 | - | | | | | | |
| 58 | 59370-8000 | - | | | | | | |
| 59 | 59370-8100 | - | | | | | | |
| 60 | 50398-8000 | - | ○ | | | | | |
| 61 | 50398-8100 | - | ○ | x | x | | | |
| 62 | 50397-8000 | - | ○ | ○ | | | | |
| 63 | 50397-8100 | - | ○ | ○ | x | | | |
| 64 | 08-70-0102 | 5241T | | | | | | |
| 65 | 08-70-0103 | 5241TL | ○ | ○ | x | | | |
| 66 | 50802-8000 | - | | | | | | |
| 67 | 50802-9001 | - | | | | | | |
| 68 | 50802-8100 | - | | | | | | |
| 69 | 50802-9101 | - | | | | | | |
| 70 | 50837-8000 | - | ○ | ○ | | | | |
| 71 | 50837-8100 | - | | | | | | |
| 72 | 50351-8000 | - | | | | | | |
| 73 | 50351-8100 | - | | | | | | |
| 74 | 50217-8000 | - | | ○ | | | | |
| 75 | 50217-9001 | - | | | | | | |
| 76 | 50217-8100 | - | | | | | ○ | ○ |
| 77 | 50217-9101 | - | | | | | ○ | ○ |
| 78 | 50539-8000 | - | | | | | | |
| 79 | 50539-8100 | - | | | | | | |
| 80 | 08-70-1031 | 5194T | | | | | | |

| | | | | | | | | |
|-----|------------|-----------|---|---|---|---|---|---|
| 81 | - | 5194PBT | | | | | | |
| 82 | - | 5225T | | | | | | |
| 83 | 08-70-1030 | 5194TL | x | ○ | x | | | ○ |
| 84 | 39-00-0022 | 5194PBTTL | x | ○ | x | | ○ | ○ |
| 85 | - | 5225TL | | | | | ○ | |
| 86 | 50597-8000 | - | ○ | ○ | | | | |
| 87 | 50598-8000 | - | | | | | | |
| 88 | 50597-8100 | - | x | ○ | ○ | x | x | ○ |
| 89 | 50598-8100 | - | | | | | | |
| 90 | 39-00-0038 | 5556T | ○ | ○ | | | | |
| 91 | 39-00-0059 | 5556PBT | | | | | | |
| 92 | 39-00-0046 | 5556T2 | | | | | | |
| 93 | 39-00-0065 | 5556PBT2 | | | | | | |
| 94 | 39-00-0077 | 5556T3 | | | | | | |
| 95 | 39-00-0079 | 5556PBT3 | | | | | | |
| 96 | 39-00-0039 | 5556TL | ○ | ○ | x | | ○ | ○ |
| 97 | 39-00-0060 | 5556PBTTL | x | ○ | x | | ○ | ○ |
| 98 | 39-00-0047 | 5556T2L | ○ | ○ | x | | | ○ |
| 99 | 39-00-0066 | 5556PBT2L | | | | | | ○ |
| 100 | 39-00-0078 | 5556T3L | x | ○ | x | | | |
| 101 | 39-00-0080 | 5556PBT3L | | | | | | |
| 102 | 39-00-0040 | 5558T | | ○ | | | | |
| 103 | 39-00-0061 | 5558PBT | | | | | | |
| 104 | 39-00-0048 | 5558T2 | | | | | | |
| 105 | 39-00-0067 | 5558PBT2 | | | | | | |
| 106 | 39-00-0081 | 5558T3 | | | | | | |
| 107 | 39-00-0083 | 5558PBT3 | | | | | | |
| 108 | 39-00-0041 | 5558TL | ○ | ○ | x | | ○ | ○ |
| 109 | 39-00-0062 | 5558PBTTL | x | ○ | x | | ○ | ○ |
| 110 | 39-00-0049 | 5558T2L | ○ | x | x | | | |
| 111 | 39-00-0068 | 5558PBT2L | | | | | | |
| 112 | 39-00-0082 | 5558T3L | | | | | | |
| 113 | 39-00-0084 | 5558PBT3L | | | | | | |
| 114 | 39-00-0281 | 1189AT | | | ○ | | | |
| 115 | 39-00-0284 | 1381AT | x | ○ | | | | |
| 116 | 39-00-0317 | 1433AT | | | | | | |
| 117 | 39-00-0289 | 1189ATL | x | x | ○ | ○ | ○ | x |
| 118 | 39-00-0308 | 1381ATL | ○ | ○ | x | | | x |
| 119 | 39-00-0318 | 1433ATL | ○ | ○ | x | | | |
| 120 | 39-00-8322 | 1433AGL | | | | | | |
| 121 | 39-00-0296 | 1190T | | | ○ | | | |
| 122 | 39-00-0283 | 1380T | x | ○ | | | | |
| 123 | 39-00-0323 | 1434T | | | | | | |

| | | | | | | | | |
|-----|-------------|----------|---|---|---|---|---|---|
| 124 | 39-00-0325 | 1434G | | | | | | |
| 125 | 39-00-0297 | 1190TL | x | x | ○ | x | x | x |
| 126 | 39-00-0302 | 1380TL | x | ○ | x | | | ○ |
| 127 | 39-00-0324 | 1434TL | ○ | ○ | | | | |
| 128 | - | 1434GL | | | | | | |
| 129 | 56279-8000 | - | | | | | | |
| 130 | 56265-8000 | - | | | | | | |
| 131 | 56265-8100 | - | | | | | | |
| 132 | 500989-1000 | - | | | | | | |
| 133 | 501395-1000 | - | | | | | | |
| 134 | 50419-9001 | - | | | | | | |
| 135 | 50419-9101 | - | | | | | | |
| 136 | 50217-9001 | - | | | | | | |
| 137 | 50217-9101 | - | | | | | ○ | |
| 138 | 39-00-0278 | 1560T | ○ | ○ | | | | |
| 139 | 39-00-0280 | 1854T | | | | | | |
| 140 | 39-00-0327 | 1560TL | ○ | ○ | x | | | |
| 141 | 39-00-0335 | 1854TL | ○ | ○ | | | | |
| 142 | 39-00-0279 | 1561T | ○ | ○ | | | | |
| 143 | 39-00-0338 | 1855T | | | | | | |
| 144 | 39-00-0331 | 1561TL | ○ | ○ | x | | | |
| 145 | 39-00-0339 | 1855TL | | | | | | |
| 146 | 50061-8000 | - | | | | | | |
| 147 | 50080-8000 | - | | | | | | |
| 148 | 50061-8100 | - | | | | | | |
| 149 | 50080-8100 | - | | | | | | |
| 150 | 50034-8000 | - | | | | | | |
| 151 | 50034-8100 | - | ○ | | | | | |
| 152 | - | 5378T | | | | | | |
| 153 | - | 5378TL | | | | | | |
| 154 | 50097-8000 | - | | | | | | |
| 155 | 50097-8100 | - | | | | | | |
| 156 | 50098-8000 | - | | | | | | |
| 157 | 50098-8100 | - | | | | | | |
| 158 | - | 5190-01T | | | | | | |
| 159 | 08-70-0106 | 5298T | | | | | | |
| 160 | 50147-8000 | - | ○ | | | | | |
| 161 | 50147-8100 | - | ○ | x | x | | | |
| 162 | 50148-8000 | - | ○ | ○ | | | | |
| 163 | 50148-8100 | - | ○ | x | x | | | |
| 164 | 50038-8000 | - | | | | | | |
| 165 | 50038-8100 | - | ○ | x | x | | | |
| 166 | 50039-8000 | - | | | | | | |

| | | | | | | | | |
|-----|-------------|-----------|---|---|---|--|--|--|
| 167 | 50039-8100 | - | ○ | ○ | × | | | |
| 168 | 50212-8000 | - | | | | | | |
| 169 | 50212-8100 | - | | | | | | |
| 170 | 50061-8000 | - | | | | | | |
| 171 | 50080-8000 | - | | | | | | |
| 172 | 50061-8100 | - | | | | | | |
| 173 | 50080-8100 | - | | | | | | |
| 174 | 50034-8000 | - | | | | | | |
| 175 | 50034-8100 | - | | | | | | |
| 176 | - | 5378T | | | | | | |
| 177 | - | 5378TL | | | | | | |
| 178 | 50097-8000 | | ○ | | | | | |
| 179 | 50097-8100 | | | | | | | |
| 180 | 50098-8000 | | ○ | ○ | | | | |
| 181 | 50098-8100 | | | | | | | |
| 182 | 08-70-0042 | 5005TL | ○ | ○ | | | | |
| 183 | 08-70-0043 | 5006TL | × | ○ | × | | | |
| | | | | | | | | |
| 184 | 39-00-0082 | 5558T3L | × | ○ | × | | | |
| 185 | 39-00-0067 | 5558-PBT2 | ○ | ○ | × | | | |
| 186 | 39-00-0061 | 5558PBT | × | ○ | × | | | |
| 187 | 50539-8000 | - | × | ○ | × | | | |
| 188 | 08-70-1031 | 5194T | × | ○ | × | | | |
| 189 | 39-00-0059 | 5556PBT | × | ○ | × | | | |
| 190 | 39-00-0079 | 5556PBT3 | × | ○ | × | | | |
| 191 | 39-00-0081 | 5558T3 | × | ○ | × | | | |
| 192 | 50802-8000 | - | ○ | ○ | × | | | |
| 193 | 39-00-0038 | 5556T | × | ○ | × | | | |
| 194 | 39-00-0278 | 1560T | × | ○ | × | | | |
| 195 | 39-00-0083 | 5558PBT3 | × | ○ | × | | | |
| 196 | 501647-1000 | - | ○ | × | × | | | |
| 197 | 50837-8000 | - | ○ | ○ | × | | | |
| 198 | 39-00-0048 | 5558T2 | ○ | × | × | | | |
| 199 | 39-00-0021 | - | × | ○ | × | | | |
| 200 | 39-00-0077 | 5556T3 | × | ○ | × | | | |
| 201 | 39-00-0040 | 5558T | × | ○ | × | | | |
| 202 | 39-00-0046 | 5556T2 | ○ | ○ | × | | | |
| 203 | 39-00-0067 | 5558-PBT2 | ○ | ○ | × | | | |
| 204 | 08-70-0102 | 5241T | ○ | ○ | × | | | |
| 205 | 50351-8000 | - | ○ | × | × | | | |
| 206 | 59370-8000 | - | ○ | × | × | | | |
| 207 | 56134-9100 | - | ○ | × | × | | | |
| 208 | 502438-0000 | - | ○ | × | × | | | |

| | | | | | | | | |
|-----|------------|----------------|---|---|---|---|---|---|
| 209 | 50038-8000 | - | ○ | × | × | | | |
| 210 | 50039-8000 | - | ○ | × | × | | | |
| 211 | 50217-9101 | - | × | ○ | × | | | |
| 212 | 39-00-0279 | 1561T | ○ | ○ | × | | | |
| 213 | 39-00-0065 | 5556PBT2 | ○ | × | × | | | |
| 214 | 50147-8000 | - | ○ | × | × | | | |
| 215 | 08-70-1039 | 5263PBT | ○ | × | × | | | |
| 216 | 50011-8000 | - | ○ | × | × | | | |
| 217 | 50012-8000 | - | ○ | × | × | | | |
| 218 | 50034-8000 | - | ○ | × | × | | | |
| 219 | 50013-8000 | - | ○ | × | × | | | |
| 220 | 50212-8000 | - | ○ | × | × | | | |
| 221 | - | 5479PBTL | | | | ○ | | |
| 222 | 43030-0007 | - | | | | ○ | ○ | ○ |
| 223 | 50212-8100 | - | | | | | | |
| 224 | 43030-0010 | - | | | | ○ | ○ | ○ |
| 225 | 50752-8100 | - | | | | ○ | ○ | ○ |
| 226 | - | - | | | | | | |
| 227 | 08-50-0106 | 2478-1-(P909)L | × | ○ | ○ | | | |
| 228 | - | - | | | | | | |
| 229 | 43030-0001 | - | | | | | | |
| 230 | 16-02-0103 | 70058-0224 | | | | | | ○ |
| 231 | - | - | | | | | | |
| 232 | 50394-8100 | - | ○ | | | ○ | | |
| 233 | - | - | | | | | | |
| 234 | 02-09-1102 | 1189-A(P901) | | | | | | |
| 235 | 02-09-1104 | 1189-A(P901)L | | | | | | |
| 236 | 02-09-5100 | 1189-A(P550) | | | | | | |
| 237 | 02-09-5102 | 1189-A(P591) | | | | | | |
| 238 | 02-09-5106 | 1189-A(P550)L | | | | | | |
| 239 | 02-09-5111 | 1189-A(P591)L | | | | | | |
| 240 | 02-09-6102 | 1189-A(P901)-I | | | | | | |
| 241 | 02-09-2101 | 1190-(P901) | | | | | | |
| 242 | 02-09-2103 | 1190-(P901)L | | | | | | |
| 243 | 02-09-5101 | 1190-(P901)-I | | | | | | |
| 244 | 02-09-6100 | 1190550 | | | | | | |
| 245 | 02-09-6101 | 1190591 | | | | | | |
| 246 | 02-09-6106 | 1190-(550)L | | | | | | |
| 247 | 02-09-6110 | 1190P591L | | | | | | |
| 248 | 02-09-2133 | 1376-(P909)L | | | | | | |
| 249 | 02-09-2134 | 1376-A(P909)L | | | | | | |
| 250 | 02-09-6132 | 1376-(558)L | | | | | | |
| 251 | 02-09-1134 | 1377-AP909L | | | | | | |

| | | | | | | | | |
|-----|------------|----------------|--|--|--|--|--|--|
| 252 | 02-09-5132 | 1377AGL | | | | | | |
| 253 | 02-09-2116 | 1380-(P901) | | | | | | |
| 254 | 02-09-2118 | 1380-(P901)L | | | | | | |
| 255 | 02-09-6122 | 1380G3 | | | | | | |
| 256 | 02-09-6123 | 1380GL3 | | | | | | |
| 257 | 02-09-6125 | 1380591 | | | | | | |
| 258 | 02-09-6126 | 1380-(591)L | | | | | | |
| 259 | 02-09-1117 | 1381-A(P901) | | | | | | |
| 260 | 02-09-1118 | 1381-(P901)L | | | | | | |
| 261 | 02-09-1119 | 1381-A(P901)L | | | | | | |
| 262 | 02-09-5130 | 1381-A(P591) | | | | | | |
| 263 | 02-09-5133 | 1381-A(P591)L | | | | | | |
| 264 | 02-09-5142 | 1381AGL3 | | | | | | |
| 265 | 02-09-5143 | 1381-A(P550) | | | | | | |
| 266 | 39-00-0308 | 1381ATL | | | | | | |
| 267 | 39-00-0316 | 1433TL | | | | | | |
| 268 | 39-00-0317 | 1433AT | | | | | | |
| 269 | 39-00-0318 | 1433ATL | | | | | | |
| 270 | 39-00-0324 | 1434TL | | | | | | |
| 271 | 02-09-8103 | 1973-A(P901) | | | | | | |
| 272 | 02-09-8104 | 1973-A(P901)L | | | | | | |
| 273 | 02-09-8108 | 1973-2A(P901) | | | | | | |
| 274 | 02-09-8109 | 1973-2A(P901)L | | | | | | |
| 275 | 02-09-1122 | 2273-A(P901) | | | | | | |
| 276 | 02-09-1123 | 2273-A(P901)L | | | | | | |
| 277 | 02-06-1101 | 1561-(P901) | | | | | | |
| 278 | 02-06-5101 | 1561-(P561) | | | | | | |
| 279 | 02-06-5104 | 1561-(P591)L | | | | | | |
| 280 | 02-06-5105 | 1561-P591 | | | | | | |
| 281 | 02-06-5108 | 1561-(P563) | | | | | | |
| 282 | 39-00-0331 | 1561TL | | | | | | |
| 283 | 02-06-5100 | 1561-(P550) | | | | | | |
| 284 | 02-06-5102 | 1561-(P561)L | | | | | | |
| 285 | 02-06-5103 | 1561-(P550)L | | | | | | |
| 286 | 02-06-5109 | 1561P563L | | | | | | |
| 287 | 02-06-1104 | 4529-(P901) | | | | | | |
| 288 | 02-06-1131 | 1855-(P901) | | | | | | |
| 289 | 02-06-5130 | 1855-(P550) | | | | | | |
| 290 | 02-06-5135 | 1855-(P550)L | | | | | | |
| 291 | 02-06-5147 | 1855-(P228) | | | | | | |
| 292 | 39-00-0338 | 1855T | | | | | | |
| 293 | 02-06-5138 | 1855-(P561) | | | | | | |
| 294 | 02-06-5139 | 1855(P561)L | | | | | | |

| | | | | | | | | |
|-----|------------|--------------|--|--|--|--|---|--|
| 295 | 02-06-5148 | 1855-(P228)L | | | | | | |
| 296 | 02-06-2101 | 1560-(P901) | | | | | | |
| 297 | 02-06-2103 | 1560-(P901)L | | | | | | |
| 298 | 02-06-6101 | 1560-(561) | | | | | | |
| 299 | 02-06-6104 | 1560-(591)L | | | | | | |
| 300 | 02-06-6118 | 1560-(228) | | | | | | |
| 301 | 02-06-6119 | 1560-(228)L | | | | | | |
| 302 | 39-00-0278 | 1560T | | | | | | |
| 303 | 39-00-0327 | 1560TL | | | | | | |
| 304 | 02-06-6100 | 1560-(550) | | | | | | |
| 305 | 02-06-6102 | 1560-(561)L | | | | | | |
| 306 | 02-06-6103 | 1560-(550)L | | | | | | |
| 307 | 02-06-2131 | 1854-(P901) | | | | | | |
| 308 | 02-06-2132 | 1854-(P901)L | | | | | | |
| 309 | 02-06-6138 | 1854-(561) | | | | | | |
| 310 | 02-06-6143 | 1854-(228) | | | | | | |
| 311 | 02-06-6144 | 1854(228)L | | | | | | |
| 312 | 39-00-0280 | 1854T | | | | | | |
| 313 | 39-00-0335 | 1854TL | | | | | | |
| 314 | 02-06-6130 | 1854-(550) | | | | | | |
| 315 | 02-06-6135 | 1854-(550)L | | | | | | |
| 316 | 02-06-6139 | 1854(561)L | | | | | | |
| 317 | 02-06-6122 | 1778-(228)L | | | | | | |
| 318 | 02-06-8103 | 1778-(P909)L | | | | | | |
| 319 | 02-06-7103 | 1779-(P909)L | | | | | | |
| 320 | 02-06-7104 | 1779-P228L | | | | | | |
| 321 | 87421-0000 | | | | | | ○ | |